



FITTING INSTRUCTIONS

1 HELMET

If the hat size is not known, using a tape measure, start one inch above the eyebrows and measure around the widest part of the head.

H MEASURE AROUND THE WIDEST PART OF THE HEAD

2 CHEST PROTECTOR

For best fit, measure from the bottom of the throat/collarbone down to just past the naval area.

A THROAT/COLLARBONE

B NAVAL AREA

3 LEG GUARDS

For best fit, measure from center of the knee to the top of foot.

C CENTER OF KNEE CAP

D TOP OF FOOT (ANKLE/SHIN JOINT AREA)

MATCH MEASUREMENTS WITH THE CLOSEST SIZE IN CHART